

AD-A060 013

HARRIS ECI ASSOCIATES WOODBRIDGE NJ

NATIONAL DAM SAFETY PROGRAM. HALEDON RESERVOIR (NJ00021), PASSA--ETC(U)

AUG 78 R GERSHOWITZ

DACW61-78-C-0124

NL

UNCLASSIFIED

1 OF 2

AD
A060013



Approved for public release;
distribution unlimited

①
LEVEL II

AD A060013

PASSAIC RIVER BASIN

MOLLY ANN BROOK, PASSAIC COUNTY


NEW JERSEY

HALEDON RESERVOIR

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

DDC FILE COPY

NJ 00021



DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE - 2D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106
AUGUST 1978

8 10 10 -087

NOTICE

**THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.**

8 10 10 077



DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE-2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO
NAPEN-D

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, New Jersey 08621

27 SEP 1978

ACCESSION for	
NTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	AVAIL. and/or SPECIAL
A	

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Haledon Reservoir in Passaic County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Haledon Reservoir Dam, a high hazard potential structure, is judged to be in good overall condition. Also, the spillway is considered seriously inadequate since 36 percent of the Probable Maximum Flood (PMF) would overtop the dam. The seriously inadequate spillway is assessed as an UNSAFE, non-emergency condition, until more detailed studies prove otherwise or corrective measures are completed. The classification of UNSAFE applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with an UNSAFE classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard of loss of life downstream from the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant, engaged by the owner, using more sophisticated methods, procedures and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1979. In the interim, a detailed emergency operation

NAREN-D

Honorable Brendan T. Byrne

plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analysis should be performed to determine the dam and spillway foundation condition and structural stability. This should include test borings to determine material properties relative to stability and seepage and installation of piezometers to facilitate seepage studies. Any remedial measures found necessary should be initiated within calendar year 1979.

c. Within six months of the date of approval of this report, the following remedial actions should be completed:

(1) All brush and trees should be removed from the downstream slope and the area seeded to develop a growth of grass for surface erosion protection.

(2) The erosion which has occurred on the upstream crest of the embankment should be repaired. An effective method of protecting the embankment from future erosion should be implemented.

d. Within three months of the date of approval of this report, the leakage through the joints of the spillway conduits and around the conduit should be repaired. Also, an Operation and Maintenance manual and program should be developed and utilized.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Robert A. Roe of the Eighth District. Under the provisions of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia, 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.


An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly

NAPEN-D

Honorable Brendan T. Byrne

request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely yours,



JAMES G. TON
Colonel, Corps of Engineers
District Engineer

1 Incl
As stated

Cy Furn:
Mr. Dirk C. Hofman, P.E.
Department of Environmental Protection
1471 Prospect Street
Trenton, New Jersey 08625

HALEDON RESERVOIR (NJ00021)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 29 June and 7 July 1978 by Harris-ECI under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

The Haledon Reservoir Dam, a high hazard potential structure, is judged to be in good overall condition. Also, the spillway is considered seriously inadequate since 36 percent of the Probable Maximum Flood (PMF) would overtop the dam. The seriously inadequate spillway is assessed as an UNSAFE, non-emergency condition, until more detailed studies prove otherwise or corrective measures are completed. The classification of UNSAFE applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with an UNSAFE classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard of loss of life downstream from the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant, engaged by the owner, using more sophisticated methods, procedures and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1979. In the interim, a detailed emergency operation plan and warning system, should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the dam and spillway foundation condition and structural stability. This should include test borings to determine material properties relative to stability and seepage and installation of piezometers to facilitate seepage studies. Any remedial measures found necessary should be initiated within calendar year 1979.

c. Within six months of the date of approval of this report, the following actions should be completed.

(1) All brush and trees should be removed from the downstream slope and the area seeded to develop a growth of grass for surface erosion protection.

(2) The erosion which has occurred on the upstream crest of the embankment should be repaired. An effective method of protecting the embankment from future erosion should be implemented.

d. Within three months of the date of approval of this report, the leakage through the joints of the spillway conduits and around the conduit should be repaired. Also, an Operation and Maintenance manual and program should be developed and utilized.

APPROVED: _____

James G. Ton
JAMES G. TON
Colonel, Corps of Engineers
District Engineer

DATE: _____

27 Sep 78

1

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Haledon Reservoir Dam, I.D. NJ00021
State Located: New Jersey
County Located: Passaic
Stream: Molly Ann Brook
Date of Inspection: June 29, and July 7, 1978

Assessment of General Condition ..

Haledon Reservoir Dam is in good condition with wet areas evident along the toe. However, no flowing seepages were found. The downstream slope is heavily overgrown with brush and trees, and there are several minor small erosions at the upstream edge of the crest due to minor riprap failures. The spillway inlet and conduits are in good condition, but there is significant leakage around the left conduit pipe at the inlet structure. There was also minor leakages into the conduits at the pipe joints.

The general condition or adequacy of Haledon Reservoir Dam is considered questionable in view of its lack of spillway capacity to pass the PMF, or even one-half of the PMF without overtopping the dam. The spillway is capable of passing a flood equal to 35% of the PMF.


At present, the engineering data available is not sufficient to make a definitive statement on the stability of the earth embankment.

The following remedial actions, therefore, are suggested along with a timetable for their completion.


1. Studies to augment the spillway discharge capacity should be undertaken within six months.
2. Repairs should be made within 3 months to stop the leakage through the joints of the spillway conduits and around the conduits in the inlet structure.

Furthermore, while of a less urgent nature, the following additional action is recommended and should be carried out within a reasonable period of time.

1. All brush and trees should be removed from the downstream slope to avoid problems which may develop from their roots. The embankment should then be seeded to develop a growth of grass for surface erosion protection.
2. A program should be developed to monitor possible seepage through the embankment.
3. The erosion which has occurred on the upstream crest of the embankment should be repaired. An effective method of protecting the embankment from future erosion should be implemented.


Robert Gershowitz, P.E.





LAKE HALEDON RESERVOIR

Dam, spillway, trash guard and water supply intake gate house.

June 29, 1978

TABLE OF CONTENTS

ASSESSMENT OF GENERAL CONDITION

		<u>Page</u>
SECTION 1	PROJECT INFORMATION	1
	1.1 General	1
	1.2 Description of Project	2
	1.3 Pertinent Data	5
SECTION 2	ENGINEERING DATA	9
	2.1 Design	9
	2.2 Construction	9
	2.3 Operation	9
	2.4 Evaluation	10
SECTION 3	VISUAL INSPECTION	12
	3.1 Findings	12
	3.2 Evaluation	15
SECTION 4	OPERATION PROCEEDURES	16
	4.1 Procedures	16
	4.2 Maintenance of Dam	16
	4.3 Maintenance of Operating Facilities	16
	4.4 Evaluation	17
SECTION 5	HYDRAULIC/HYDROLOGIC	18
	5.1 Evaluation of Features	18
SECTION 6	STRUCTURAL STABILITY	21
	6.1 Evaluation of Structural Stability	21

TABLE OF CONTENTS

(Continued)

	<u>Page</u>
SECTION 7 ASSESSMENT/REMEDIAL MEASURES	24
7.1 Dam Assessment	24
7.2 Remedial Measures	25
7.3 Recommendations	26

PLATES

	<u>No. .</u>
VICINITY MAP	1
GEOLOGIC MAP	2
DAM DRAWINGS	3-4

APPENDICES

APPENDIX A	-	CHECK LIST - VISUAL OBSERVATIONS CHECK LIST - ENGINEERING, CONSTRUCTION MAINTENANCE DATA
APPENDIX B	-	PHOTOGRAPHS
APPENDIX C	-	SUMMARY OF ENGINEERING DATA
APPENDIX D	-	HYDROLOGIC COMPUTATIONS
APPENDIX E	-	STABILITY CALCULATIONS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

HALEDON RESERVOIR, ID. NJ00021

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The National Dam Inspection Act (Public Law 92-367, 1972) provides for the National Inventory and Inspection Program by the U.S. Army Corps of Engineers. This inspection was made in accordance with this authority under Contract C-FPM No. 35 with the State of New Jersey who, in turn, is contracted to the Philadelphia District of the Corps of Engineers.

b. Purpose of Inspection

The visual inspection of the Haledon Reservoir was made on June 29, and July 7, 1978. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project; presents a summary of visual observations made during the Field Inspection; presents an evaluation of hydrologic and hydraulic conditions at the site; presents an evaluation as to the structural adequacy of the various project features; and assesses the general condition of the dam with respect to safety.

1.2 Description of Project

a. Description of Dam and Appurtenances

Haledon Reservoir Dam is a rolled earth embankment with vertical concrete core wall. The dam has a straight axis with overall length of about 625 feet, and an embankment height of about 25 feet. The core wall is completely covered by the earthfill. The crest of the dam is 10 feet wide, is paved with asphalt and is used only as a footpath. The upstream and downstream slopes both are 2 horizontal to 1 vertical. The upstream face of the dam is protected by 12 inches of rock riprap.

The original plans for the dam called for the concrete core wall to extend 3 feet into firm rock to form a cutoff. The embankment was to be placed on natural ground after about 2 feet of topsoil had been removed.

The intake structure and raw water supply line to the Haledon Municipal Water Treatment Plant constitutes the outlet works for the reservoir. The intake structure is a reinforced concrete rectangular tower located in the reservoir

at the upstream toe near the right abutment. Four 12-inch diameter pipes through the upstream tower wall provide multi-level inlets to the intake tower. Each of the inlet pipes has a screen on the outside and a control gate in the wet well inside the tower. A concrete block masonry building on top of the concrete structure provides weather protection for the equipment inside the tower. A 16-inch diameter water supply pipeline passes directly under the embankment and connects directly to the water treatment plant. A maximum of 2.5 million gallons per day can be passed through the water treatment plant. There is no bypass or branch outlet on the supply pipeline.

The emergency spillway is an ungated drop inlet and triple conduit under the embankment. The drop inlet is rectangular in plan with the long axis parallel to the dam and outside dimensions of 21 feet 5 inches by 12 feet 8 inches. The rim of the drop inlet is a broad-crested weir 8 inches wide and is 4 feet below the crest of the dam. A concrete trashrack structure surrounds the drop inlet structure to keep out logs. The top of the trashrack is 1 foot above the crest of the drop inlet. The invert of the drop box at the conduit is 9.4 feet below the crest. The conduits discharge, through a reinforced concrete headwall structure, into a short, well-defined natural channel with rocky bottom and wooded slopes. A small lower pond is only about 60 feet from the toe of Haledon Reservoir Dam. The pond is formed by a low dam less than 25 feet high and the pond storage is less than 50 acre-feet.

b. Location

Haledon Reservoir is located in Passaic County, New Jersey, and is accessible by way of High Mountain Road. The dam is on land owned by the Borough of Haledon with private roadway access to the left abutment.

c. Size and Hazard Classification

Haledon Reservoir is classified in the dam size category as being "small", since its storage is less than 1,000 acre-feet and its height is less than 40 feet. Since failure of the dam could cause loss of life and extensive property damage, a hazard potential classification of "high" has been assigned to the project.

d. Ownership

Haledon Reservoir is owned by the Borough of Haledon, 408 Morrissee Avenue, Haledon, New Jersey.

e. Purpose of Dam

Haldeon Reservoir is the source of raw water for the Borough of Haledon water treatment plant, and no other use of the lake or dam is allowed.

f. Design and Construction History

The dam was designed and constructed in 1926. A few drawings and hydraulic calculations prepared at that time by A. W. Cuddeback, for the Borough of Haledon, are available from the New Jersey Department of Environmental Protection. No computations for the design of the embankment or structures

are available for review. It was reported by the owner's representative that the WPA made some improvements in the 1930's, but the details of the improvements were not known to him. The present structure closely resembles the 1926 plans so that the nature of the improvements is not readily apparent.

g. Normal Operational Procedures

The discharge from the reservoir is normally regulated by the water treatment plant to meet its raw water requirements. The policy is to keep as much water as possible in the reservoir. Therefore, the water level varies primarily according to rainfall. The normal variation is only a few feet with occasional drops to 6 or 7 feet. Rarely is the reservoir nearly drained during drought periods such as occurred in 1947.

1.3 Pertinent Data

a. Drainage Area - 1.6 square miles

b. Discharge at Damsite

Maximum known flood at damsite	N.A.
Warm water outlet at pool elevation	N.A.
Diversion tunnel low pool outlet at pool elevation	N.A.
Diversion tunnel outlet at pool elevation	N.A.
Gated spillway capacity at pool elevation	N.A.
Gated spillway capacity at maximum pool elevation	N.A.

Ungated spillway capacity at maximum pool elevation 750 cfs
(El. 416.06)

Total spillway capacity at maximum pool elevation 750 cfs

c. Elevation (Feet above MSL)

Top of dam	416.06
Maximum pool-design surcharge	416.06
Full flood control pool	N.A.
Water supply pool	412
Spillway crest	412
Upstream portal invert diversion tunnel	N.A.
Downstream portal invert diversion tunnel	N.A.
Streambed at centerline of dam	20' \pm (Estimated)
Maximum tailwater	N.A.

d. Reservoir

Length of maximum pool	4,000 feet (Estimated)
Length of water supply pool	2,800 feet (Estimated)
Length of flood control pool	N.A.

e. Storage (Acre-Feet)

Water supply pool	657 acre-feet (El. 412)
Flood control pool	N.A.
Design surcharge	823 acre-feet (El. 414.35)
Top of dam	979 acre-feet (El. 416.06)

f. Reservoir Surface (Acres)

Top of dam	99 acres (El. 416.06)
Maximum pool	83 acres (El. 414.35)
Flood control pool	N.A.
Water supply pool	58 acres (El. 412)
Spillway crest	58 acres (El. 412)

g. Dam

Type	Embankment with concrete core wall
Length	625 feet
Height	25 feet
Top width	10 feet
Side slopes	2 horizontal to 1 vertical
Zoning	Core wall with rolled earthfill shells
Impervious core	Core wall
Cutoff	Core wall
Grout curtain	None

h. Diversion and Regulating Tunnel (N.A.)

i. Spillway

Type	Drop inlet and conduits
Conduits	Three 42-inch diameter concrete conduits
Crest elevation	412

1
Gates

N.A.

Upstream channel

Reservoir

Downstream channel

Well defined channel with some cobble and
boulder protection

j. Regulating Outlets

Four 12-inch diameter inlets provided with sluice gates and one 16-inch diameter outlet conduit, located at the right end of the dam. The outlet supplies water to the filter plant and may not be used for the purpose of reservoir drawdown.

SECTION 2: ENGINEERING DATA

2.1 Design

A set of drawings for alternative designs for the dam and spillway structures were available in the files of the New Jersey Department of Environmental Protection. A few hydraulic calculations for the spillway design were available also. The plans for the concrete core wall and earthfill alternative correspond well to the present structures as observed.

2.2 Construction

No records have been found as to the construction history of the dam. The source and quality of the embankment materials is unknown. The plans called for rolled embankment, but the moisture content and compaction equipment used are not known.

2.3 Operation

Records of daily flows through the water treatment plant and reservoir level are kept by the plant operators.

2.4

Evaluation

a. Availability

The availability of engineering data is very poor. The only data available are the drawings pertaining to original alternative plans for the dam and spillway, which can be obtained from the New Jersey Department of Environmental Protection. The "as-built" spillway dimensions are as shown on Plate 4, and not as shown on Plate 3.

b. Adequacy

The available engineering data is not sufficient to perform a comprehensive, definitive stability analysis of the embankment. Data needed to fully assess the stability of the dam includes:

1. Subsurface information at the damsite, including engineering properties and parameters of the bed-rock.
2. Soil properties of the embankment.
3. Location of the phreatic line within the dam section at several cross section lines including the maximum section.
4. Verification of, and the vertical extent of the core wall.

A check list of engineering construction and maintenance data is included in Appendix A.

c. Validity

The field inspection appears to substantiate the available plans and sections to the extent that could be determined by visual observations.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

The visual inspection made of Haledon Reservoir Dam did not reveal any signs of distress in the dam or appurtenances. The dam appeared to be in reasonably good condition and adequately maintained.

b. Dam

The embankment appeared to be made up of cohesionless soil. The geometry of the embankment conforms to the 1926 plans with a 2 to 1 downstream slope and a 10 foot wide crest. The upstream slope was below water level at the time of the inspection. The downstream slope was heavily overgrown with brush and trees up to 8 inches in diameter. The upstream slope also supported a growth of brush and weeds near the crest. A paved road, with several longitudinal cracks, lies along the crest, however, the cracks are not believed to be related to movement of the dam. No evidence of vertical or horizontal movement of the dam was detected.

The dam appears to have been raised about 1 foot with granular material. The top 3 to 4 feet of riprap appear hand placed and form a near 1 to 1 slope. Erosion appears to have removed soil from four locations on the crest; the first near the right side of the spillway; the last approximately

100 feet farther right. The areas are semi-circular, 3 to 5 feet in diameter and about 2 to 3 feet deep. Numerous minor riprap failures are apparent near the crest.

Basalt is exposed in the left side of the discharge channel. The basalt is broken into fragments averaging 2 inches in size. The slopes mantling the basalt contain silt, clay and coarse granular material to the size of boulders. The right abutment is made up of red sandstone of the Brunswick Formation.

No flowing seepage was observed on the slope, along the toe or further downstream of the dam. Standing water was observed near the toe of the dam about 50 feet right of the discharge channel. The water table was found to be about 6 inches below ground surface along the toe of the dam, however, this could be attributed to the small impoundment immediately downstream of the dam. Water was observed flowing from the right abutment about 100 feet downstream of the dam, but is not believed related to the dam, rather, may be attributed to ground water runoff from a nearby hillside or an abandoned storm sewer.

c. Appurtenant Structures

1. Spillway

The concrete drop inlet structure and surrounding concrete trashrack are in excellent condition. No evidence of structural cracking or spalling could be found. Most of the joints in the precast concrete pipe conduits are leaking small quantities of clear water all

around the pipe. The joint between the outside of the left conduit and the drop inlet wall was leaking several gallons per minute of clear water.

2. Outlet Works

Only the upper few feet of the concrete intake tower and the covering concrete block building were visible to inspect. The structural concrete and block masonry appears in good condition. The control gates and raw water supply line could not be inspected. The four slide gates located in the outlet gate house are all functional and appear to be well maintained and in very good condition.

d. Reservoir Area

The reservoir rim is gently sloped and no indications of instability were readily apparent. The slopes above the reservoir are heavily wooded. No buildings or dwellings are built on or near the shoreline.

e. Downstream Channel

The downstream channel is well defined, free of vegetation and protected by numerous cobbles and boulders. The side slopes vary from steep to moderate and support trees and brush. Only minor erosion could be observed in a few areas.

3.2 Evaluation

At the time of the inspection the dam did not exhibit any signs of distress. The abutments appeared to be in good condition. Overall, the dam appears to be in good condition. Reservoir slopes show no apparent signs of instability and are not believed a potential hazard to the dam.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

Because the Haledon Reservoir Dam is used to impound water for the Borough of Haledon water treatment plant, the policy is to maintain as much water as possible in the reservoir. Thus, water is released normally only through the treatment plant. The spillway releases excess flow during storms after the reservoir has been filled.

4.2 Maintenance of the Dam

The dam is under daily surveillance by the water treatment plant personnel. Repairs are made by the Public Works Department of the Borough of Haledon as they deem necessary.

4.3 Maintenance of Operating Facilities

Regular maintenance of the gates, valves and equipment in the intake structure and raw water supply line is performed by the treatment plant operators.

4.4 Evaluation

Maintenance of the facility is in the hands of the Borough of Haledon, Department of Public Works. The procedures are on a simple, as-needed basis. In view of the greater public interest in dam safety, the following procedures should be initiated.

1. An annual visual inspection of the dam utilizing the Corps of Engineers check list conducted by the Borough's engineering representative or the DPW supervisor.
2. Formal daily logging of reservoir levels.
3. Formal logging of maintenance at dam, be it repairs, inspection or reservoir dredging.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design

Haledon Dam is located on the northeast corner of the Borough of North Haledon. The drainage area above the Haledon Dam on the Molly Ann Brook is 1.6 square miles. A drainage map of the watershed of Haledon damsite is presented on Plate 1, Appendix D.

Elevations within the watershed range from approximately 412 feet above mean sea level at the damsite to over 500 feet above mean sea level in the upper portion of the watershed.

Land use patterns within the watershed are mostly urban with some forested lands in the areas near the reservoir. Most of the urban areas are located along the main streets and highways.

The evaluation of the hydraulic and hydrologic features of Haledon Dam was based on criteria set forth in the Corps guidelines and additional guidance provided by the Philadelphia District, Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation using Hydrometeorological Report No. 33 with standard reduction factors. Due to the small drainage area of Haledon Dam, the SCS triangular hydrograph, transformed to a curvilinear hydrograph, was adopted for developing the unit hydrograph. The derived unit hydrograph is presented in Appendix D.

Initial and infiltration loss rates were applied using SCS procedure to the Probable Maximum Storm rainfall to obtain rainfall excesses. The rainfall excesses were then applied to the unit hydrograph to obtain the PMF hydrograph utilizing program HEC-1.

The computed peak discharges of PMF and one-half the PMF are 7,920 cfs and 3,960 cfs, respectively.

Both the PMF and one-half the PMF inflow hydrographs were routed through the reservoir by the Modified Puls Method, also utilizing computer program HEC-1. The peak outflow discharges for the PMF and one-half the PMF are 6,478 cfs and 2,054 cfs, respectively. Both the PMF and one-half the PMF result in overtopping of the dam.

The stage-outflow relation for the spillway was prepared from field notes, sketches and limited construction drawings. The reservoir stage-capacity data were based on the U.S.G.S. quadrangle topographic maps in combination with data given in the National Dam Safety Inventory Table. Reservoir storage capacity include for surcharge levels exceeding the top of the dam and the spillway rating curve assumed that the dam remains intact during routing. In the routing computations, the discharge through outlet facilities was excluded due to its insignificant magnitude as compared to the spillway discharge and the PMF. The spillway rating curve and the reservoir capacity curve are presented in Plates 2 and 3 of Appendix D, respectively.

b. Experience Data

No records of reservoir stage or spillway discharge are maintained for this site. However, according to the owner of the dam, the maximum reservoir level was never higher than the crest of the embankment.

c. Visual Observation

The spillway structure and the approach channel are well defined. No new urbanization was noted in the reservoir area. The downstream channel is also well defined with heavy riprap along river banks, but with thick tree growth.

d. Overtopping Potential

As indicated in Section 5.1-a., both the Probable Maximum Flood and one-half the Probable Maximum Flood, when routed through Haledon Lake Reservoir result in overtopping the dam. The spillway and reservoir surcharge capacities are too small to accommodate the peak flows. The PMF and one-half the PMF overtopped the dam by 2.09 feet and 0.54 feet, respectively. The spillway is only capable of passing a flood equal to approximately thirty-five percent of the PMF without overtopping the dam. Since one-half the PMF is the minimum Spillway Design Flood (SDF) for this dam, according to the Recommended Guidelines for Safety Inspection of Dams by the Corps of Engineers, the spillway capacity of the Haledon Dam is considered "Inadequate".

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

There are no signs of embankment sloughing, rock slides or slumps on the downstream side. The upstream side of the embankment was almost completely under water and was not accessible for visual inspection. Some erosion, as described in Section 3.1b, was observed near the crest on the upstream side.

Neither the spillway drop inlet nor the discharge headwall exhibited any evidence of undermining or misalignment.

b. Design and Construction Data

No design computations were uncovered during the report preparation phase. No embankment or foundation soil parameters are available for carrying out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction are available for use in the stability analysis.

c. Operating Records

No operating records are available relating to the stability of the dam.

d. Post-Construction Changes

There are no records of post-construction changes. It was orally reported that improvements were made to the dam in the 1930's by the W.P.A., but the exact nature of the work was unknown.

From the visual inspection it appeared that the dam crest was raised about 1 foot with granular material.

e. Static Stability

A static stability analysis was performed on a section, as defined in the 1926 Plan, titled Borough of Haledon Water Improvements, to better assess the adequacy of the structure. Bishop's method of slices was used with assumed parameters for the embankment and foundation materials. The phreatic surface was taken at normal water surface elevation upstream and assumed horizontal at ground elevation from the downstream toe back to the core wall. No failure circles were passed through the core wall. The validity of the results are, of course, a function of the assumptions made. The results, which are given in Appendix E, did yield an acceptable factor of safety for both the deep and shallow failure arcs analyzed. The following parameters were assumed:

Fill Material and Foundation

Friction Angle = 30°

Moist Unit Weight = 125 p.c.f.

Saturated Unit Weight = 130 p.c.f.

Several faults, mapped by others, occur west of the dam, the closest being about 2,500 feet. The dam is located in Seismic Zone 1, as defined in Recommended Guidelines For Safety Inspection of Dams as prepared by the Corps of Engineers. In general, projects located in Seismic Zones 0, 1 and 2 may be assumed to present no hazard from earthquake, provided the static stability conditions are satisfactory and conventional safety margins exist.

SECTION 7: ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

a. Safety

The dam has been inspected visually and a review has been made of the available engineering data. This assessment is subject to the limitation inherent in the visual inspection procedures stipulated by the Corps of Engineers for a Phase I report.

The safety of Haledon Reservoir Dam is in question because the dam does not have an adequate spillway capacity to pass the PMF or even one-half of the PMF without overtopping. Overtopping of the dam carries with it the danger of possible progressive failure of the embankment. The dam's present spillway capacity can pass only about 35 percent of the PMF.

No definitive statement pertaining to the safety of the embankment can be made without acquisition of embankment and foundation material engineering properties and determination of phreatic levels in the downstream part of the embankment. The present embankment, however, has performed adequately since its construction in 1926 without failure or evidence of instability. The stability analysis, with its limitations, does not reveal potential for serious slope failure. The possibility of minor sloughing may exist, particularly in the event of seismic excitation.

The leakages into and around the spillway conduits should be stopped to prevent possible loss of fines from embankment material.

b. Adequacy of Information

The information and data uncovered is not adequate to perform a comprehensive, definitive evaluation of the dam's stability. Nevertheless, in view of the past performance of the dam, its present condition, and in light of the stability calculations performed, it is not felt that additional information on the engineering properties of the embankment and foundation materials is necessary at this time.

c. Urgency

Studies to augment the spillway discharge capacity should be undertaken within six months.

The repairs to stop spillway conduit leakages should be undertaken within three months.

7.2 Remedial Measures

a. Alternatives

The alternative available for increasing the spillway capacity are:

1. Increasing the dam height, thus permitting a higher discharge to pass through the spillway without overtopping.

2. Enlarging the existing spillway to accomodate a flood peak of at least one-half the PMF.
3. A combination of any of the above alternatives.

The conduit leakages can be stopped best by pressure grouting in the earth embankment behind the joints through holes drilled in the concrete.


7.3 Recommendations

Based on the visual inspection and data evaluation presented herein, the following action is recommended.


1. All brush and trees should be removed from the downstream slope to avoid problems which may develop from their roots. The embankment should then be seeded to develop a growth of grass for surface erosion protection.
2. O & M Procedures: The owner should initiate a program of annual inspections of Haledon Reservoir Dam, and the small storage pond dam utilizing the standard visual check list in this report. Headwater and tailwater gages should be installed in the dam, and read out during severe rainstorms and at routine operating and maintenance visits to the dam. A program should be developed to monitor possible seepage through the embankment. A permanent log should be kept of all maintenance and operating events of the dam, lake and outlet passages.

3. The erosion which has occurred on the upstream crest of the embankment should be repaired. An effective method of protecting the crest from future erosion should be implemented.

PLATES




VICINITY MAP



LEGEND


- Rb BRUNSWICK FORMATION
RED SANDSTONE WITH INTERBEDS OF SOFT, RED SHALE
- Rbs BASALT
- F FAULT

GEOLOGIC MAP HALEDON DAM




To be excavated to a depth of 2 ft


PLAN
1:300



SECTION A-A OF DAM
Scale 1/32 = 1'0"




Cross-section view of the dam structure. The vertical axis represents elevation in feet, with markings at 60, 70, 80, and 90. The horizontal axis represents stationing, with markings at 0+00, 1+00, 2+00, 3+00, and 4+00. A solid line represents the dam's internal structure, and a dashed line represents the ground surface. A vertical line is drawn at station 1+00, labeled "El 101".



NOTE: 4 conduits are shown but only 3 conduits were constructed as shown on the following drawing.

PLAN
1-300



BOROUGH OF HALEDON

WATER WORKS IMPROVEMENTS

GENERAL LAYOUT FOR EARTH DAM



Scales as noted


March 1-1926

Amundtback
Engineer

SHEET NO

PLATE 3





BOROUGH OF HALEDON

WATER WORKS IMPROVEMENTS

WELLWAY DETAILS

Scale 1/4" = 1'

Aug 5 1926

Engineer

[Signature]

APPENDIX A

CHECK LIST - VISUAL OBSERVATIONS

CHECK LIST - ENGINEERING, CONSTRUCTION
MAINTENANCE DATA

CHECK LIST

Visual Inspection
Phase I

Name Dam Haledon Reservoir County Passaic State New Jersey Coordinators _____

Date(s) Inspection June 29, 1978 Weather Clear-Warm Temperature 75°F

Pool Elevation at Time of Inspection _____ M.S.L. Tailwater at Time of Inspection _____ M.S.L.

Inspection Personnel:

(June 29, 1978)

Joe Sirianni

(June 29, 1978)

William Flynn

(July 7, 1978)

Yin Au-Yeung

Henry King

Lynn Brown

David Kerkes

Robert B. Campbell Recorder

Owner Representative:

(June 29, 1978)

Fred Peloso, Superintendent Public Works
Borough of Haledon

CONCRETE/MASONRY DAMS

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEEPAGE OR LEAKAGE	N.A. (Not Applicable)	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	N.A.	
DRAINS	N.A.	
WATER PASSAGES	N.A.	
FOUNDATION		

CONCRETE/MASONRY DAMS

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	N.A.	
STRUCTURAL CRACKING	N.A.	
VERTICAL AND HORIZONTAL ALIGNMENT	N.A.	
MONOLITH JOINTS	N.A.	
CONSTRUCTION JOINTS	N.A.	

EMBANKMENT

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Crest covered with asphalt paving having several major longitudinal cracks not believed related to movement of dam. One small hole found which might have been made by snake or animal burrowing in embankment. Embankment heavily covered with brush and vines.	Remove brush and vines from slope and toe of embankment. Annual inspection for burrowing animals and snakes, and trap or poison if found.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	No surficial evidence of movement or cracking at or beyond toe.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Crest appears to have been raised about 1 foot with gravelly soil. Four small erosions at upstream crest 3 to 5 feet diameter, semi-circular and 2-3 feet deep located from right side of spillway to 100 feet right of spillway. Minor riprap failures at these locations. No sloughing or erosion of abutment slopes found.	Repair riprap failures and backfill erosions. Repair asphalt paving on crest.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	No evidence of movement found.	Establish horizontal and vertical alignment survey monuments on both slopes near crest. Annually run survey to detect changes.
RIPRAP FAILURES	Top 3 to 4 feet of riprap appears hand placed forming 1:1 sloping soil packed rubble wall. Riprap below maximum water surface is loose. Minor riprap failures at numerous locations along embankment, especially near crest.	Repair all riprap failures.

EMBANKMENT

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
TREES	Large trees with 6 to 8 inch diameter trunks growing on downstream slope of embankment.	Trees should be cut and downstream slope kept clear of trees to prevent large root systems from penetrating embankment.
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Both abutments look good. No evidence of erosion can be found.	
ANY NOTICEABLE SEEPAGE	Some wet and/or seep areas noticed along toe but no flowing water could be found. Standing water found in one place approximately 50 feet right of spillway outlet.	Inspect area below dam monthly to detect changes in wet areas.
STAFF AND GAGE RECORDER	None at time of inspection.	Reinstall staff gage.
DRAINS	None.	

OUTLET WORKS

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Concrete tower structure is in good shape.	
INTAKE STRUCTURE	Concrete rectangular tower with four 12-inch diameter multi-level pipes through tower wall. Pipes have trash bars across front. Outlet from tower is through 12-inch diameter discharge pipe.	
OUTLET STRUCTURE	None - 16 inch discharge pipeline connects directly to water treatment plant.	
OUTLET CHANNEL	None.	
EMERGENCY GATE	None - Only low-level outlet is through the treatment plant. There is no bypass around treatment plant. 2-1/2 MGD maximum can be passed through the plant. Clarifier has overflow but capacity is not known.	Valves and bypass line should be installed to enable draw-down of reservoir without having to go through treatment plant.

UNGATED SPILLWAY

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Rectangular perimeter overflow wier wall with 8" wide flat top. Concrete surfaces in excellent condition. No structural cracks visible. Outer concrete trash rack structure installed about 8 years ago. Spillway is drop inlet type. Spillway discharge is carried through three conduits.	Minor seeps through joints around drop structure can be seen. No repair believed required.
APPROACH CHANNEL	None - Spillway inlet is out in the reservoir with approach from all around.	
DISCHARGE CHANNEL	Outlet of conduits is out of concrete headwall structure. Concrete headwall is in excellent condition. Downstream channel is a natural, rocky channel with gentle sideslopes.	
BRIDGE AND PIERS	None.	
CONCRETE PIPE CONDUITS	Three concrete pipe conduits carry spillway flow under embankment. All pipes are leaking through joints near axis of dam between 2-5 gpm. Large leak of about 20 gpm flow into drop structure around the left pipe. All flows are clear water. Concrete surfaces of pipe are in good condition.	Leakages around left pipe into drop structure into pipes at joints should be stopped.

GATED SPILLWAY
(None)

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N.A.	
APPROACH CHANNEL	N.A.	
DISCHARGE CHANNEL	N.A.	
BRIDGE AND PIERS	N.A.	
GATES AND OPERATION EQUIPMENT	N.A.	

INSTRUMENTATION

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None	
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER	None	

RESERVOIR

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Gently sloping away from lake. Slopes are heavily wooded and appear stable.	
SEDIMENTATION	No significant evidence of sediment found but some sedimentation reported by water superintendent. The Department of Public Works is contemplating agreeing to allow a developer to excavate sediment within reservoir for use as fill material.	
SHORELINE STRUCTURES	No dwellings on or near shorelines. Department of Public Works, Borough of Haledon owns 100 feet around lake shore.	
USE	Reservoir is raw water storage for the municipal water system for the Borough of Haledon.	
OPERATION	Normal variation is only a few feet with occasional drop to 6 or 7 feet. Level varies according to rainfall. Lake was virtually drained in 1947 drought. Reservoir is about 14 feet deep.	

DOWNSTREAM CHANNEL

Haledon Reservoir

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Very short channel to small lower lake. Well defined natural channel. Wooded slopes with rocky bottom. The lower lake is only about 60 feet from the toe of Haledon Dam.	
SLOPES	Sideslopes very gentle and heavily wooded.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	None - Water treatment plant is beyond lower site.	

CHECK LIST
ENGINEERING DATA

DESIGN, CONSTRUCTION, OPERATION

Haledon Reservoir

ITEM	REMARKS
PLAN OF DAM	Original construction plan is available.
REGIONAL VICINITY MAP	Available.
CONSTRUCTION HISTORY	Original construction history not available.
TYPICAL SECTIONS OF DAM	Available on plans listed above.
HYDROLOGIC/HYDRAULIC DATA	None available.
OUTLETS - PLAN) None Available.
- DETAILS) None Available.
- CONSTRAINTS) Maximum discharge through treatment plant - 2.5 mgd.
- DISCHARGE RATINGS) None Available.
RAINFALL/RESERVOIR RECORDS	None Available.

CHECK LIST
ENGINEERING DATA

DESIGN, CONSTRUCTION, OPERATION
(Continued)

Haledon Reservoir

ITEM	REMARKS
DESIGN REPORTS	None available.
GEOLOGY REPORTS	None available.
DESIGN COMPUTATIONS) None Available.
HYDROLOGY & HYDRAULICS) Available for the spillway conduits but not to "present-day" standards.
DAM STABILITY) None Available.
SEEPAGE STUDIES) None Available.
MATERIALS INVESTIGATIONS)
BORING RECORDS) None available.
LABORATORY)
FIELD)
POST-CONSTRUCTION SURVEYS OF DAM	None Available.
BORROW SOURCES	Unknown. Appear to be from local sources.
SPILLWAY - PLAN)
- SECTIONS) None available for existing spillway.
- DETAILS)

CHECK LIST
ENGINEERING DATA

DESIGN, CONSTRUCTION, OPERATION
(Continued)

Haledon Reservoir

ITEM	REMARKS
OPERATING EQUIPMENT PLANS AND DETAILS) None available.)
MONITORING SYSTEMS	None available.
MODIFICATIONS	Unknown.
HIGH POOL RECORDS	None available.
POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Dam inspected and report prepared by State of New Jersey in 1961.
PRIOR ACCIDENTS OR FAILURE OF DAM - DESCRIPTION - REPORTS	None Reported.
MAINTENANCE, OPERATION RECORDS	Daily flow records through treatment plant.

APPENDIX B

PHOTOGRAPHS

(All photos were taken on June 29, 1978.)

Haledon Reservoir




Photo 1 - View of dam from upstream left shoreline.



Photo 2 - View of crest of dam from left abutment.

Haledon Reservoir




Photo 3 - Upstream slope of dam showing brush and vine overgrowth. Note thin log which is stuck in inlet.




Photo 4 - View of downstream slope of dam showing heavy brush and timber growth on embankment.




Photo 5 - Intake gate house for water supply to treatment plant.




Photo 6 - Rectangular drop-inlet spillway intake and concrete trash guard.

Haledon Reservoir




Photo 7 - Three 42-inch diameter concrete pipe conduits in spillway drop-inlet structure. Note thin log resting across outlets.




Photo 8 - View of spillway outlet conduits and headwall.

Haledon Reservoir



Photo 9 - Discharge channel from
spillway outlet.



Photo 10 - Downstream channel to lower impoundment.

Haledon Reservoir




Photo 11 - Haledon Reservoir and left shoreline.



Photo 12 - Haledon Reservoir and right shoreline.

APPENDIX C

SUMMARY OF ENGINEERING DATA

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

Name of Dam: Haledon Reservoir Dam
Drainage Area: 1.6 square miles
Elevation Top Normal Pool (Storage Capacity): 412. (657 AF)
Elevation Top Flood Control Pool (Storage Capacity): Not applicable
Elevation Maximum Design Pool: 414.35
Elevation Top of Dam: 416.06

SPILLWAY CREST:

- a. Elevation: 412
- b. Type: Drop Inlet Spillway
- c. Width: Not applicable
- d. Length: Three 42 inch conduits
- e. Location Spillover: Left end of the dam
- f. Number and Type of Gates: None

OUTLET WORKS:

- a. Type: Four 12-inch dia. inlets provided w/sluice gates and one 16-inch dia. conduit outlet
- b. Location: Right end of the dam
- c. Entrance Inverts: 406.82 (upper 2-12"); 398.75 (lower 2-12"); 391.73 (16" main)
- d. Exit Inverts: Not applicable
- e. Emergency Draindown Facilities: None (the outlet supplies water to filter plant)

HYDROMETEOROLOGICAL GAGES: (None)


- a. Type: _____
- b. Location: _____
- c. Records: _____

MAXIMUM NON-DAMAGING DISCHARGE: 750 cfs (Estimated)

APPENDIX D

HYDROLOGIC COMPUTATIONS

PLATE 1, APPENDIX-D



HALEDON RESERVOIR DAM
DRAINAGE MAP

ECI-4

ENGINEERING CONSULTANTS, INC.

1. JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 1 OF 7


HALEDON RESERVOIR DAM

JOB NO. 1212-001

SPILLWAY & OVERTOP RATING CURVE

BY J.M.G.

DATE 8-3-71



NEW JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 2 OF 7

HALEDON RESERVOIR DAM

JOB NO. 1212-001

SPILLWAY & OVERTOP RATING CURVE

BY MAS DATE 8-3-71

SPILLWAY DISCHARGES (Assuming no tailwater effect)

W.L. at EL 98 (413.06 MSL)

a) Weir flow:

Assume $C = 3.03$

$$Q = CLH^{1.5} = 3.03 \times 60 \times 1.06^{1.5} \\ = 198 \text{ cfs.}$$

b) Permissible flow through the pipe

$$\text{Slope of pipe} = S = \frac{3.15}{\sqrt{54.9^2 - 3.15^2}}$$

$$S = \frac{3.15}{54.81} = 0.0575$$

Critical Slope:

$$Q = \frac{198}{3} = 66 \text{ cfs.}$$

$$Z = \frac{Q}{\sqrt{g}} = \frac{66}{\sqrt{32.2}} = 11.63$$

$$\frac{Z}{d_o^{2.5}} = \frac{11.63}{3.5^{2.5}} = 0.51$$

$$\text{for } \frac{Z}{d_o^{2.5}} = 0.51, \frac{y_c}{d_o} = 0.73 \Rightarrow y_c = 2.56'$$

$$S_c = \left(\frac{Qn}{1.49AR^{2/3}} \right)^2$$

Assume $n = 0.013$

ENGINEERING CONSULTANTS, INC.

NEW JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 3 OF 7

HALEDON RESERVOIR DAM

JOB NO. 1212-001

SPILLWAY & OVERTOP RATING CURVE

BY MAS DATE 8-3-71

Lin

$$\frac{y_c}{d_0} = 0.73 \Rightarrow \frac{A}{A_0} = 0.79 \text{ \& } \frac{R}{R_0} = 1.2$$

$$\text{where } A_0 = 0.7854 d_0^2 = 0.7854 \times 3.5^2 \\ = 9.62'$$

$$R_0 = 0.25 d_0 = 0.25 \times 3.5 = 0.88'$$

$$A = 0.79 \times 9.62 = 7.6 \text{ sft}$$

$$R = 1.2 \times 0.88 = 1.06 \text{ ft}$$

$$\therefore S_c = \left(\frac{66 \times 0.013}{1.49 \times 7.6 \times 1.06^{2/3}} \right)^2 \\ = 0.0053 < S$$

Pipe slope is supercritical

Critical depth may occur at the inlet to the pipe and the flow through the pipe may be supercritical flow

$$\therefore \boxed{Q_{sp} = 198 \text{ cfs}}$$

NEW JERSEY (STATE) DAM SAFETY INSPECTION SHEET NO. 4 OF 7
 HALEDON RESERVOIR DAM JOB NO. 1212-001
 SPILLWAY & OVERTOP RATING CURVE BY MAS DATE 8-3-71

W.L. at EL 99.3 (414.06 MSL)

a) Weir flow:

$$Q = 3.08 \times 60 \times 2.06^{1.5} \\ = 538 \text{ cfs}$$

b) Permissible discharge through the pipe:

$$Q = \frac{538}{3} = 179 \text{ cfs}$$

$$Z = \frac{Q}{\sqrt{g}} = \frac{179}{\sqrt{32.2}} = 31.54$$

$$\frac{Z}{d_o^{2.5}} = \frac{31.54}{3.5^{2.5}} = 1.38 \Rightarrow \frac{Y_c}{d_o} = 0.98$$

$$\Rightarrow Y_c = 3.43'$$

$$\frac{Y_c}{d_o} = 0.98 \Rightarrow \frac{A}{A_o} = 0.99$$

$$\& \frac{R}{R_o} = 1.05$$

$$A = 0.99 \times \frac{\pi}{4} \times (3.5)^2 = 9.52 \text{ ft}^2$$

$$R = \frac{1}{4} (3.5) \times 1.05 = 0.92$$

$$S_c = \left(\frac{179 \times 0.013}{1.49 \times 9.52 \times 0.92^{0.67}} \right)^2 = 0.0301 < 0.0575$$

As the critical depth is $\geq d_o$, and the inlet is rounded check for pressure flow.

ENGINEERING CONSULTANTS, INC.

NEW JERSEY (STATE) DAM SAFETY INSPECTION SHEET NO. 5 OF

HALEDON RESERVOIR DAM

JOB NO. 1212-001

SPILLWAY & OVERTOP RATING CURVE

BY MAS DATE 8-3-7

Pressure flow:

$$H_T = \left(1 + K_e + f \frac{L}{D}\right) \frac{V^2}{2g}$$

Assume $K_e = 0.10$;

& $f = .021$ for $n = .013$

$$\begin{aligned} \therefore H_T &= \left(1 + .10 + \frac{.021 \times 54.9}{3.5}\right) \frac{V^2}{2g} \\ &= 1.43 \frac{V^2}{2g} \end{aligned}$$

$$\therefore V = \frac{\sqrt{2gH_T}}{1.43} = 0.84 \sqrt{2gH_T}$$

$$\begin{aligned} Q &= AV = 0.84 A \sqrt{2gH_T} \\ &= 0.84 \times \frac{\pi}{4} (3.5)^2 \sqrt{64.4 \times (99.864)} \\ &= 0.84 \times 0.785 (3.5)^2 \sqrt{64.4 \times 12.86} \\ &= 232 \text{ cfs} \end{aligned}$$

$$Q_T = 232 \times 3 = 696 \text{ cfs} > 538 \text{ cfs}$$

$$Q_{sp} = 538 \text{ cfs}$$

NEW JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 6 OF 7

HALGSON RESERVOIR DAM

JOB NO. 1212-001

SPILLWAY & OVERTOP RATING CURVE

BY MAS DATE 8-3-7

W.L. at EL 100 (415.06 MSL)

a) Weir flow:

$$Q = 2.03 \times 60 \times 3.06^{1.5}$$

$$= 973 \text{ cfs.}$$

b) Maximum open channel flow

$$Q_T \approx 533 \text{ cfs}$$

c) Pressure flow:

$$Q = 0.84 A \sqrt{2gH_T}$$

$$= 0.84 \times 0.785 \times 3.5^2 \sqrt{64.4 \times 13.86}$$

$$= 241 \text{ cfs}$$

$$Q_T = 723 \text{ cfs} < 973 \text{ cfs}$$

d) Sluice flow: As the inlet is somewhat rounded sluice flow may not occur

$$\therefore Q_{sp} = 723 \text{ cfs}$$

W.L. at EL 101

$$Q_{sp} = 0.84 \times 3 \times 0.785 \times 3.5^2 \sqrt{64.4 \times 14.86}$$

$$Q_{sp} = 750 \text{ cfs}$$

USE THE FOLLOWING EQUATION FOR SPILLWAY
DISCHARGES FOR W.L. ABOVE EL 101.

$$Q_{sp} = 3(0.84 A \sqrt{2gH_T})$$

NEW JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 7 OF 7

HALSDON RESERVOIR DAM

JOB NO. 1212-001


SPILLWAY & OVERTOP RATING CURVE

BY MAS DATE 8-3-71

TOTAL SPILLWAY & OVERTOP DISCHARGES

Reference Elev. (Assumed elev.)	Head on Spilling Crest Fe.	H _T	H ₁	L ₁	C ₁	Discharge through Spillways, Q _{sp} , cfs	Discharge over the top of dam Q _t = C ₁ L ₁ H ₁ ^{1.5} cfs	Total Discharge Q _{sp} + Q _t cfs
96.94 (412)	0							0
98 (413.06)	1.06					198		198
99 (414.06)	2.06					538		538
100 (415.06)	3.06	13.6				723		723
101 (416.06)	4.06	14.6	0			750		750
102 (417.06)	5.06	15.6	1	600	3.03	774	1818	2,592
103 (418.06)	6.06	16.6	2	600	3.03	798	5142	5,940
104 (419.06)	7.06	17.6	3	600	3.03	822	9446	10,268
105 (420.06)	8.06	18.6	4	600	3.03	845	14,544	15,389

Lin



HALEDON RESERVOIR DAM
SPILLWAY AND OVERTOP
RATING CURVE

ENGINEERING CONSULTANTS, INC.

NEW JERSEY (STATE) DAM SAFETY INSPECTION SHEET NO. 1 OF
 HALEDON RESERVOIR DAM JOB NO. 1212-001
 RESERVOIR AREA-CAPACITY DATA BY MAS DATE 8-4-

HALEDON RESERVOIR DAM RESERVOIR AREA CAPACITY DATA

Maximum Storage = 823 AF


Normal Storage = 657 AF

Reservoir Surface Area = 58 acres at
 Elev 412 (from USGS topo map)

Reservoir Surface Area = 140 acres at EL 420

Assumed Elev (MS) Ft.	Reservoir Surface Area Acres	Reservoir Volume AF	Remarks
412 (Spillway Crest)	58	657	The normal volume of 657 AF is assumed at the crest of the drop inlet spillway
414.35	83±	823	
416.06 (Top of dam)	99	979	
420	140	1450	

PLATE 3, APPENDIX D



HALEDON RESERVOIR DAM
RESERVOIR CAPACITY CURVE

NEW JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 1 OF

HALEDON RESERVOIR DAM

JOB NO. 1211-001

SYNTHETIC UNIT HYDROGRAPH

BY RCL DATE 6-30

UNIT HYDROGRAPH - HALEDON RESERVOIR DAM

A) DRAINAGE AREA, $A = 1.6 \text{ sq mi.}$

B) $L = 1.17 \text{ miles}$

$$C) T_c = \left[\frac{11.9 L^3}{\Delta H} \right]^{0.385} = \left[\frac{11.9 (1.17)^3}{123} \right]^{0.385}$$

$$= 0.49 \text{ hrs} = 0.50 \text{ hrs.}$$


D) Assume $D \approx \frac{1}{2} T_c = 0.25 \text{ hrs.}$

$$E) T_p = \frac{D}{2} + 0.6 T_c$$

$$= 0.125 + 0.6 (0.50) = 0.425 \text{ hrs} \approx 0.43 \text{ hrs.}$$

F) $T_b = 2.67 T_p = 1.14 \text{ hrs.}$

$$G) q_p = \frac{484 A}{T_p} = \frac{484 (1.6)}{0.43} = 1801 \text{ cfs}$$



ENGINEERING CONSULTANTS, INC.

NEW JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 2 OF

HALEDON RESERVOIR DAM


JOB NO. 1212-001

UNIT HYDROGRAPH

BY MAS DATE 6-30-7

H) CURVILINEAR UNIT HYDROGRAPH

TIME RATIO T/T_p	DISCHARGE RATIO q/q_p	UNIT GRAPH	
		TIME, T hrs.	DISCHARGE q CFS
0	0	0	0
0.1	0.015	0.043	27
0.2	0.075	0.086	135
0.3	0.16	0.13	288
0.4	0.28	0.17	504
0.5	0.43	0.22	774
0.6	0.60	0.26	1081
0.7	0.77	0.30	1387
0.8	0.89	0.34	1603
0.9	0.97	0.39	1747
1.0	1.00	0.43	1801
1.1	0.98	0.47	1764
1.2	0.92	0.52	1657
1.3	0.84	0.56	1573
1.4	0.75	0.60	1357
1.5	0.66	0.65	1188
1.6	0.56	0.69	1009
1.8	0.42	0.77	756
2.0	0.32	0.86	576
2.2	0.24	0.95	432
2.4	0.18	1.03	324
2.6	0.13	1.12	234
2.8	0.098	1.20	177
3.0	0.075	1.29	135
3.5	0.036	1.57	65
4.0	0.018	1.72	32
4.5	0.009	1.94	16
5.0	0.004	2.15	7



HALEDON RESERVOIR
0.25 HR. UNIT HYDROGRAPH

PMP FORMATION - Haleden DAM

SHEET NO. _____ OF _____

Probable Maximum Precipitation

JOB NO. 212

BY YIN

DATE July 1978

PROBABLE MAXIMUM FLOOD CALCULATION (PMP)

Drainage = 1.6 sq. mi.

From Hydrometeorological Report "33" Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Duration of 6, 12, 24 and 48 Hours, 1966

For D.A. = 10 sq. mi.

6 hour rain fall duration.

PMP = 25.0" for Zone "6" at Haleden Basin.

Since D.A. < 10 sq. mi., No area reduction to be applied.

PMP Values for various rain fall duration

Duration	PMP (inch)
6 hr.	25.0"
12 hr.	27.25"
24 hr.	29.25"
48 hr.	31.50"

PMP values are reduced by 20% to account for misalignment of Basin and storm Isohyets.

Duration
6 hr.
12 hr.
24 hr.
48 hr.

PMP
20.0"
21.8"
23.6"
25.4"

THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC

Can be neglected.

ECI-4 ENGINEERING CONSULTANTS, INC.

NEW JERSEY DAM SAFETY INSPECTION (DWP)
 PMF DERIVATION - HALSEY DAM
 PROBABLE MAXIMUM PRECIPITATION

SHEET NO. _____ OF _____
 JOB NO. 1212
 BY YIN DATE _____

$$DA = 1.6$$

PMP. PMF DERIVATION.

1) SOIL GROUP "C", & AMC = II.

2) CN = 85.

MIN LOSS RATE FOR ABOVE CONDITIONS is 0.12"/hr.

FOR CN = 85,

$S = 1.76$ in the

$$\text{eg. } Q = (P - 0.25)^2 / P + 0.85$$

$$\text{or } Q = \frac{(P - 0.362)^2}{P + 1.408}$$

THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDG

ENGINEERING CONSULTANTS, INC.

NEW JERSEY DAM SAFETY INSPECTION - (DEP) SHEET NO. 1 OF

PMF DERIVATION - HELEDON DAM

JOB NO. 1212-001-1

DIRECT RUNOFF

BY KLB DATE 7-28-78

DIRECT RUNOFF INCREMENTS FOR COMPUTING PMF

TIME ENDING (HR)	INCREMENTAL DESIGN RAINFALL (IN)	ACCUMUL - ATIVE DESIGN RAINFALL (IN)	DIRECT RUNOFF ACCUMUL - ATIVE (IN)	INCRE - MENTAL (IN)	INCREMENTAL LOSS
0.25	0.50	0.50	0.01	0.00	0.01
0.50	0.50	1.00	0.17	0.16	0.34
0.75	0.50	1.50	0.45	0.28	0.22
1.00	0.50	2.00	0.80	0.35	0.15
1.25	0.60	2.60	1.26	0.46	0.14
1.50	0.60	3.20	1.76	0.50	0.10
1.75	0.60	3.80	2.28	0.52	0.08
2.00	0.60	4.40	2.82	0.54	0.06
2.25	0.75	5.15	3.51	0.69	0.06
2.50	0.75	5.90	4.21	0.70	0.05
2.75	0.75	6.65	4.92	0.71	0.04
3.00	0.75	7.40	5.64	0.72	0.03*
3.25	1.77	9.17	7.35	1.74	0.03
3.50	1.78	10.95	9.09	1.75	0.03
3.75	2.28	13.23	11.33	2.25	0.03
4.00	1.77	15.00	13.08	1.74	0.03
4.25	0.70	15.70	13.77	0.67	0.03
4.50	0.70	16.40	14.46	0.67	0.03
4.75	0.70	17.10	15.16	0.67	0.03
5.00	0.70	17.80	15.85	0.67	0.03
5.25	0.55	18.35	16.39	0.52	0.03
5.50	0.55	18.90	16.94	0.52	0.03
5.75	0.55	19.45	17.49	0.52	0.03
6.00	0.55	20.00	18.03	0.52	0.03

* MINIMUM LOSS RATE = $0.12''/\text{HR} = 0.03/1.25\text{HR}$
 (AFTER THIS LEVEL IS REACHED, ABANDON CURVE FOR $0.03''/1.25\text{HR}$ LOSS)

HEC-1 - COMPUTATIONS

ENGINEERING CONSULTANTS, INC.

NEW JERSEY (STATE) DAM SAFETY INSPECTION SHEET NO. 1 OF

HALEDON RESERVOIR

JOB NO. 1212-001-1

INPUT TO HEC-1

BY KLB

DATE 8-4-71

INPUT TO HEC-1

#	ELEV (FT)	HEAD ABOVE SPIILLWAY (FT)	Y2 STORAGE (AC-FT)	Y3 DISCHARGE (CFS)
1	412.0 (SPIILLWAY CREST)	0.00	657.	0.
2	414.0	2.00	794.	550.
3	415.0	3.00	881.	725.
4	415.5	3.50	929.	738.
5	415.9	3.90	967.	744.
6	416.06 (TOP OF DAM)	4.06	978.	750.
7	416.1	4.10	987.	750.
8	416.5	4.50	1028.	1800.
9	417.0	5.00	1083	3000.
10	419.0	7.00	1325	10260

HEC-1 VERSION DATED JAN 1973

DAM SAFETY INSPECTION - NEW JERSEY STATE
HALLEON RESERVOIR
PMF FLOOD ROUTING

JOB SPECIFICATION
NQ NHR NMN IDAY IHR IMIN METRC IPLT IPRT NSTAN
50 0 15 0 0 0 0 0 0 0 0
JOPER 0 NMT
3 0

***** SUB-AREA RUNOFF COMPUTATION *****

INPUT UNIT HYDROGRAPH DERIVED FROM SCS METHOD

ISTAG ICOMP IECON ITAPE JPLT JPRT INAME
8 0 0 0 0 0 1

HYDROGRAPH DATA
IHYDG IUNG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
0 -1 1.60 0.00 1.60 0.00 0.000 0 0 1 0

PRECIP DATA
NP STORM UAJ DAK
24 0.00 0.00 0.00

PRECIP PATTERN
0.00 0.16 0.26 0.35 0.46 0.50 0.52 0.54 0.59 0.67 0.70
0.71 0.72 1.74 1.75 2.25 1.74 0.87 0.67 0.67 0.67
0.52 0.52 0.52

LOSS DATA
STKR DLTKR RTIOL ERAIN STRKS RTIOL STRTL CNSTL ALSMX RTIMP
0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00

0. 910. 1801. 830. 350. 150. 75. 40. 20. 5.
UNIT GRAPH TOTALS 4191. CFS OR 1.01 INCHES OVER THE AREA

RECESSION DATA
STRTO= 0.00 .ORCSN= 0.00 RTIOR= 1.00

END-OF-PERIOD FLOW
TIME RAIN EXCS COMP 0
1 0.00 0.00 0.
2 0.16 0.16 0.
3 0.26 0.26 143.
4 0.35 0.35 542.
5 0.46 0.46 995.
6 0.50 0.50 1338.
7 0.52 0.52 1598.
8 0.54 0.54 1935.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	7920.	3088.	1497.	1497.	74893.
INCHES		17.95	18.14	18.14	18.14
AC-FT		1532.	1548.	1548.	1548.

ROUTE HYDROGRAPH THKU HALEUON RESEKVOIR

ISTAQ	ICOMP	IECON	IIAPE	JPLT	JPRI	INAME
8	1	0	0	2	0	1

1946 OCT 14 1447 AM DENVER, COLORADO 96225

RUNOFF SUMMARY, AVERAGE FLOW

HYDROGRAPH AT ROUTED TO	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
8	7920.	3088.	1497.	1497.	1.60
8	6478.	2527.	1427.	1427.	1.60

TEOTI

ON SOUTHERN AVENUE, N. W. COR. OF AVENUE 121

HEL-1 VERSION DATED JAN 1973

DAM SAFETY INSPECTION - NEW JERSEY STATE
HALEDON RESERVOIR
ONE HALF PMF FLOOD ROUTING

JOB SPECIFICATION
NQ NHR NMIN IDAY IHR IIRIN METRC IPLT IPRT NSTAN
50 0 15 0 0 0 0 0 0 0
JUPEM 0 NWT
3 0

***** SUB-AREA RUNOFF COMPUTATION *****

INPUT UNIT HYDROGRAPH DERIVED FROM SCS METHOD

ISTAQ ICOMP IECUN ITAPE JPLT JPRT INAME
8 0 0 0 0 0 1
HYDROGRAPH DATA
INPDSG IUNG TAREA SNAP TRSLA INSPC RATIO ISNOW ISAME LOCAL
0 -1 1.60 0.00 1.60 0.00 0.500 0 0 0
PRECIP DATA
NP STORM UAJ DAK
24 0.00 0.00 0.00
PRECIP PATTERN
0.00 0.16 0.28 0.35 0.46 0.50 0.52 0.54 0.69 0.70
0.71 0.72 1.74 1.75 2.25 1.74 0.67 0.67 0.67 0.67
0.52 0.52 0.52

LOSS DATA
SIRKR DLTKR RTIOL ERAIN STRKS RTIOL STRTL CNSTL ALSMX RTIMP
0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00
0. 910. 1801. 830. 360. 150. 75. 40. 20. 5.
UNIT GRAPH TOTALS 4191. CFS OR 1.01 INCHES OVER THE AREA

RECESSION DATA
STRTO# 0.00 GRCSW# 0.00 RTIOR# 1.00

END-OF-PERIOD FLOW

TIME	RAIN	LXCS	COMP	Q
1	0.00	0.00	0.	0.
2	0.16	0.16	0.	0.
3	0.28	0.28	145.	0.
4	0.35	0.35	542.	0.
5	0.46	0.46	955.	0.
6	0.50	0.50	1358.	0.
7	0.52	0.52	1698.	0.
8	0.54	0.54	1935.	0.

AD-A060 013

HARRIS ECI ASSOCIATES WOODBRIDGE NJ

NATIONAL DAM SAFETY PROGRAM. HALEDON RESERVOIR (NJ00021), PASSA--ETC(U)

AUG 78 R GERSHOWITZ

DACW61-78-C-0124

NL

UNCLASSIFIED

2 OF 2

AD
A060013



END

DATE
FILMED

12-78

DDC

9	0.69	0.69	2088.
10	0.70	0.70	2321.
11	0.71	0.71	2649.
12	0.72	0.72	2816.
13	1.74	1.74	2914.
14	1.75	1.75	3098.
15	2.25	2.25	5770.
16	1.74	1.74	7102.
17	0.67	0.67	7920.
18	0.67	0.67	6601.
19	0.67	0.67	4510.
20	0.67	0.67	3552.
21	0.52	0.52	3151.
22	0.52	0.52	2841.
23	0.52	0.52	2481.
24	0.52	0.52	2306.
25	0.00	0.00	2228.
26	0.00	0.00	1727.
27	0.00	0.00	779.
28	0.00	0.00	341.
29	0.00	0.00	151.
30	0.00	0.00	72.
31	0.00	0.00	31.
32	0.00	0.00	13.
33	0.00	0.00	2.
34	0.00	0.00	0.
35	0.00	0.00	0.
36	0.00	0.00	0.
37	0.00	0.00	0.
38	0.00	0.00	0.
39	0.00	0.00	0.
40	0.00	0.00	0.
41	0.00	0.00	0.
42	0.00	0.00	0.
43	0.00	0.00	0.
44	0.00	0.00	0.
45	0.00	0.00	0.
46	0.00	0.00	0.
47	0.00	0.00	0.
48	0.00	0.00	0.
49	0.00	0.00	0.
50	0.00	0.00	0.

SUM	17.87	17.87	74895.
6-HOUR	3088.	1497.	74893.
24-HOUR	17.95	18.14	16.24
72-HOUR	1532.	1598.	1548.

RUNOFF MULTIPLIED BY 0.50			
PEAK	271.	477.	669.
CFS	1949.	2885.	3551.
INCHES	1153.	1114.	843.
AC-FT	0.	0.	0.
6-HOUR	1544.	748.	849.
24-HOUR	8.97	9.07	3960.
72-HOUR	766.	774.	37496.

1511 SOUTH WYANDOM AVENUE, DENVER, CO 80233

.....

HYDROGRAPH ROUTING

ROUTE HYDROGRAPH TIKU MALEDUN RESERVOIR

ISTAG ICOMP IECON IIAPE JPLT JPRT INAME
8 1 0 0 2 0 1

WLOSS CLOSS AVG IRES ISAME
0.0 0.000 0.00 1 0

NSTPS NSTUL LAG AFSKK X TSK STORA
0 0 0 0.000 0.000 0.000 -1.

STORAGE= 657. 794. 881. 929. 967. 978. 987. 1028. 1083. 1325.
OUTFLOW= 0. 550. 725. 738. 744. 750. 750. 1600. 3000. 19258.

TIME	LOP	STOR	AVG	IN	LOP	OUT
1	657.	0.	0.	0.	0.	0.
2	657.	0.	0.	0.	0.	0.
3	657.	36.	36.	16.	16.	2.
4	661.	172.	172.	374.	44.	44.
5	668.	374.	374.	573.	67.	67.
6	678.	573.	573.	759.	140.	140.
7	692.	759.	759.	908.	201.	201.
8	707.	908.	908.	1005.	265.	265.
9	723.	1005.	1005.	1102.	332.	332.
10	739.	1102.	1102.	1241.	404.	404.
11	757.	1241.	1241.	1365.	481.	481.
12	776.	1365.	1365.	1432.	533.	533.
13	795.	1432.	1432.	1703.	600.	600.
14	819.	1703.	1703.	2417.	674.	674.
15	855.	2417.	2417.	3218.	732.	732.
16	907.	3218.	3218.	3755.	745.	745.
17	970.	3755.	3755.	4630.	1643.	1643.
18	1020.	4630.	4630.	5630.	2054.	2054.
19	1039.	5630.	5630.	6266.	2880.	2880.
20	1059.	6266.	6266.	6826.	3066.	3066.
21	1082.	6826.	6826.	7493.	356.	356.
22	1025.	7493.	7493.	789.	11.	11.
23	1018.	789.	789.	731.	3.	3.
24	1011.	731.	731.	727.	0.	0.
25	1006.	727.	727.	714.	0.	0.
26	1000.	714.	714.	685.	0.	0.
27	989.	685.	685.	630.	0.	0.
28	977.	630.	630.	630.	0.	0.
29	964.	630.	630.	630.	0.	0.
30	950.	630.	630.	630.	0.	0.
31	935.	630.	630.	630.	0.	0.
32	920.	630.	630.	630.	0.	0.
33	905.	630.	630.	630.	0.	0.
34	890.	630.	630.	630.	0.	0.
35	875.	630.	630.	630.	0.	0.
36	861.	630.	630.	630.	0.	0.
37	847.	630.	630.	630.	0.	0.
38	834.	630.	630.	630.	0.	0.

ESTIMATED FLOW, FPM, 1000 CFS

39	821.	0.	604.
40	809.	0.	580.
41	797.	0.	556.
42	786.	0.	518.
43	775.	0.	477.
44	766.	0.	439.
45	757.	0.	404.
46	749.	0.	372.
47	742.	0.	342.
48	735.	0.	315.
49	729.	0.	290.
50	723.	0.	267.
SUM			34360.

	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
PEAK	1005.	687.	687.	34360.
CFS	6.31	8.32	8.32	
INCHES	536.	710.	710.	
AC-FT				

FOOT

UNIT 50010 - MAY 2000 DEVEN'S COLLEGE - 40223

RUNOFF SUMMARY, AVERAGE FLOW

HYDROGRAPH AT ROUTED TO	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
6	3960.	1544.	746.	746.	1.60
6	2034.	1085.	637.	637.	1.60

100' SOUTH RAILROAD STATION

100' SOUTH RAILROAD STATION

MLC-1 VERSION DATED JAN 1978

DAM SAFETY INSPECTION - NEW JERSEY STATE
HALEDON RESERVOIR
PERCENT OF PMF FLOOD ROUTING

JOB SPECIFICATION
NO NHK NMN IDAY IHR IMIN METRC IPLT IPRI NSTAN
50 0 15 0 0 0 0 0 0 0 0 0
JUPEK NWT
3 0

SUB-AREA RUNOFF COMPUTATION

INPUT UNIT HYDROGRAPH DERIVED FROM SCS METHOD

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISAME	ISNOW	RATIO	LOCAL
0	0	0	0	0	0	1	0	0	0.350	0

HYDROGRAPH DATA

IMYDG	IUNG	TAREA	SNAP	IRSDA	INSPL	STRKS	KILOK	STRIL	CNSTL	ALSMX	RTIMP
0	-1	1.60	0.00	1.60	0.00	0.00	0.00	0.00	0.00	0.00	0.00

LOSS DATA

STRKR	DLTKR	RTIOL	ERAIN	STRKS	KILOK	STRIL	CNSTL	ALSMX	RTIMP
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

RECESSION DATA

STRTOZ	0.00	ORLSN	0.00	RTIOR	1.00
--------	------	-------	------	-------	------

END-OF-PERIOD FLUM

TIME RAIN EXCS COMP Q

SUM 17.07 17.07 74895.

ROUTE HYDROGRAPH TMRU HALEDON RESERVOIR

HYDROGRAPH ROUTING

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISAME	ISNOW	RATIO	LOCAL
0	1	0	0	0	0	1	0	0	0.350	0

ROUTING DATA

IMYDG	IUNG	TAREA	SNAP	IRSDA	INSPL	STRKS	KILOK	STRIL	CNSTL	ALSMX	RTIMP
0	-1	1.60	0.00	1.60	0.00	0.00	0.00	0.00	0.00	0.00	0.00

LOSS DATA

STRKR	DLTKR	RTIOL	ERAIN	STRKS	KILOK	STRIL	CNSTL	ALSMX	RTIMP
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

RECESSION DATA

STRTOZ	0.00	ORLSN	0.00	RTIOR	1.00
--------	------	-------	------	-------	------

END-OF-PERIOD FLUM

TIME	RAIN	EXCS	COMP	Q
SUM	17.07	17.07	74895.	

LAG APSKK X TSK STORA
0 0.000 0.000 -1.

STORAGE=
OUTFLOW

637.	794.	881.	929.	967.	978.	987.	1028.	1008.	1428.
0.	550.	725.	730.	744.	750.	950.	1800.	3000.	10260.

.....

1967

1967

RUNOFF SUMMARY, AVERAGE FLOW


HYDROGRAPH AT ROUTED TO	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
•	2772.	1001.	524.	524.	1.60
•	744.	762.	671.	671.	1.60




1111 SOUTH NAVAJO DENVER COLORADO 80203


APPENDIX F

STABILITY CALCULATIONS



HALEDON RESERVOIR DAM SAFETY INSPECTION






-10.00 0.00 10.00 20.00 30.00 40.00 50.00 60.00 70.00

SCALE: 1" = 10'

NEW JERSEY GROUP 2 AUG. 1978

3



HALEDON RESERVOIR DAM SAFETY INSPECTION

* 1.37 TL
 * 1.46 TL * 1.35 TL
 * 1.63 TL * 1.46 TL * 1.39 TL
 * 1.93 TL * 1.50 TL * 1.42 TL * 1.21 TL
 * 1.93 TL * 1.64 TL * 1.59 TL * 1.35 TL
 * 2.07 TL * 1.84 TL * 1.62 TL * 1.54 TL * 1.27 TL
 * 1.73 TL * 1.71 TL * 1.47 TL * 1.16 TL
 * 1.95 TL * 1.86 TL * 1.39 TL
 * 1.39 TL * 1.39 TL

Y FACTOR = $\frac{\tan \phi}{\tan i}$
 = 1.15


SOIL PARAMETERS ASSUMED
 $\phi = 30^\circ$, $\gamma_{WET} = 125$ PCF, $\gamma_T = 130$ PCF

CORE WALL

0.00 -50.00 -40.00 -30.00 -20.00 -10.00 0.00 10.00 20.00 30.00
 X-AXIS

AM SAFETY INSPECTION NEW JERSEY GROUP 2 AUG.

2



-10.00 0.00 10.00 20.00 30.00 40.00 50.00 60.00 70.00

SCALE: 1" = 10'

W JERSEY GROUP 2

AUG. 1978

3

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00021	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Haledon Reservoir Passaic County, N.J.	5. TYPE OF REPORT & PERIOD COVERED FINAL	
7. AUTHOR(s) Robert Gershowitz P.E.	8. CONTRACT OR GRANT NUMBER(s) DACW61-78-C-0124	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Harris-ECI Associates 453 Amboy Ave. Woodbridge, N.J. 07095	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106	12. REPORT DATE August, 1978	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	15. SECURITY CLASS. (of this report) Unclassified	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) National Dam Safety Program. Haledon Reservoir (NJ00021), Passaic River Basin, Molly Ann Brook, Passaic County, New Jersey. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam--N.J. National Dam Safety Program Phase I Haledon Reservoir Dam, N.J. Dam Inspection Dam Safety		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		